



AFLOAT REPAIRS



Complete Tank Cleaning to Eliminate Contamination

Overview:

We recently completed a double bottom tank cleaning that included an inspection and painting of external hatches. The client that we worked with on this project is a repeat customer which demonstrates our high standards and quality work.

We handpicked an experienced team to fulfil the job on time and we delivered a professional working standard throughout that was praised by the Chief Engineer.

Scope of Works:

- 15-P D.B Tank
- 15-C D.B
- 15-S D.B Tank
- Clean bilge tank
- Inspection of the above
- External hatches painted

Result:

The largest obstacle during the project was the restricted tank space and the limitation of entry during maneuvering. Though our experienced personnel were able to work around the ship schedule and work in switch teams in the restricted space to achieve optimum output and complete the job safely.

The job was successfully completed and comprised of consistent communication that contributed to an outstanding quality of work. The client needed a professional tank cleaning service that followed excellent safety standards so that the vessel could load new fuel without the risk of contamination.

CLIENT: Cruise Ship Management

VESSEL: Cruise Ship

DATE: March 2019

LOCATION: Caribs

1656

MANHOURS

6

PERSONNEL

25

DAYS

0

ACCIDENTS

Client Feedback:

"Professional throughout all work. Excellent time keeping and excellent continued working standard.

Recommended for future projects".

- Chief Engineer